



## Fuel Lab Technician

### **SUMMARY**

Responsible for performing various overhaul and repair duties on manifolds, nozzles, pumps, valves, etc. in accordance with WGPW established methods and practices.

**ESSENTIAL DUTIES AND RESPONSIBILITIES include** but are not limited to the following:

Perform disassembly and cleaning of various accessories

Perform basic inspection of the various accessories.

Perform assembly and testing of various accessories.

### **QUALIFICATIONS**

To perform this job successfully, an individual must be able to perform each essential duty satisfactorily. The requirements listed below are representative of the knowledge, skill, and/or ability required. Reasonable accommodations may be made to enable individuals with disabilities to perform the essential functions.

### **EDUCATION and/or EXPERIENCE**

Equivalent to high school plus additional broad specialized training and one to three years related experience; or equivalent combination of education and experience.

### **LANGUAGE SKILLS**

Ability to read and interpret documents such as safety rules, operating and maintenance instructions and procedure manuals.

### **MATHEMATICAL SKILLS**

Ability to apply the basic concepts of shop math.

### **REASONING ABILITY**

Ability to solve practical problems using pre-existing standards. Ability to interpret a variety of instructions furnished in written, oral, diagram or schedule form.

### **OTHER SKILLS AND ABILITIES**

Must have good mechanical skills and a high level of manual dexterity including hand-eye coordination. Must be able to read, interpret, document and use manufacturer's technical manuals, service bulletins, Must be able to effectively and safely use manufacturer's special tooling and lift and turn equipment.

### **PHYSICAL DEMANDS**

While performing the duties of this job, the employee is regularly required to stand, and use hands to finger, handle or feel objects, tools and controls. The employee is occasionally required to walk; sit; reach with hands and arms; stoop, kneel, or crouch; and talk or hear. The employee must occasionally lift and move up to 50 pounds. Specific vision abilities required by this job include close vision, distance vision, color vision, peripheral vision, depth perception and ability to adjust focus.

### **WORK ENVIRONMENT**

While performing the duties of this job the employee mainly works in a controlled shop lab environment.

NO PHONE CALLS PLEASE. EOE/M/F/D/V